Eink

Quick start guide for THOR 8.14″ E Ink Spectra ™ 3100

Panel and THOR EVK Connection SOP

Assembly and Operating Instructions **Demo Kit Hardware Description** ① Attach the panel to THOR ⁽²⁾ Connect the mini-USB to THOR Mini USB ector ③ Connect the mini-USB to USB power ④ Press SW2 Next image ⑤ Press SW3 White image [©] Press SW4 Previous image SW5 ⑦ Press SW5 White/Black/Red/Yellow image Function Button SW1 Reset SW2 Next image SW3 White image SW4 Previous image **Disassembly Instructions** SW5 White/Black/Red/Yellow image ① Disconnect the mini-USB ⁽²⁾ Disconnect the mini-USB ③ Detach the panel from from USB power from THOR THOR

We Make Surfaces Smarter TM